Material Safety Data Sheet U.S. Department of Labor May be used to comply with Occupational Safety and Health Administration OSHA's Hazard Communication Standard, (Non-Mandatory Form) 29 CFR 1910.1200. Standard must be Form Approved consulted for specific requirements OMB No. 1218-0072 Identity (As used on Label and List) Note: Blank spaces are not permitted. If and item CLIMÁX 901 is not applicable, or no information is available, the space must be marked to indicate that.

	space must be marked to indicate that.
Section I	
Manufacturer's Name	Emergency Telephone Number
CLIMAX LUBRICANTS & EQUIPMENT CO.	281-482-2282
Address (Number, Street City, State and ZIP Code)	Telephone Number for Information
7915 EAST ELM ST.	713-923-2626
HOUSTON,TX (USA) 77012	Verification Date
WEB ADDRESS - www.climaxlube.com	01/01/2014
E-MAIL- sales@climaxlube.com	Signature of Preparer (optional)
Manufactured/Country of Origin - U.S.A.	STEPHEN D. FRAUENBERGER

Section II – Hazardous Ingredients/Identity Information

Hazardous Component	OSHA PEL	ACGIH TLV	Other Limits	%
(Specific Chem. Identity: Common Name(s)			Recommended	(Optional)
CASTOR OIL	N/A	N/A	N/A	50-100
CAS # 8001-79-4NON-TOXIC / NON-HAZARDOUS	NON-PETROLEUM	HYDROCARBON		
POLYDIMETHYLSILOXANE-(SILICONE POLYMER)	N/A	N/A	N/A	30-0
CAS # 63148-62-9NON-TOXIC / NON-HAZARDOUS.	NON-PETROLEUN	I HYDROCARBON		
PYROGENIC SILICA	N/A	N/A	N/A	15-0
CAS # 112945-52-5				
MOLYBDENUM DISULFIDE	N/A	N/A	N/A	5-0
CAS #1317-33-5				
NFPA: HEALTH (1), FLAMMABILITY (0), REACTIVITY	(0), SPECIAL (N/A)			
NOTE: DOES NOT CONTAIN V.O.C.'S (VOLITILE ORGA	NIC COMPOUNDS)			

Section III - Physical / Chemical Characteristics

Boiling Point	N/A	Specific Gravity	1.02
		(H2O=1)	
Vapor Pressure (mm Hg.)	UNKNOWN	Melting Point	NON-
			DROPPING
Vapor Density (AIR=1)	N/A	Evaporation Rate	N/A
		(BUTYL ACETATE=1)	
Solubility in Water			
INSOLUBLE			
Appearance and Odor			

BLACK / ODORLESS

Section IV – Fire and Explosive Hazard Data

Flash Point (Method Used)	Flammable Limits	LEL	UEL
+500 DEG. FARENHITE	N/A	N/A	N/A
Extinguishing Media			
STANDARD DRY CHEMICAL, FOAM, CO-2, WATER-FOG			
Special Fire Fighting Procedures			
WEAR A NIOSH / MSHA APPROVED SELF CONTAINED BREATHING APPA	RATUS AND FULL PROTECTIVE CLO	OTHING.	
COOL CONTAINERS EXPOSED TO FIRE WITH WATER.			
Unusual Fire and Explosion Hazards			
-NONE-			

Section V - Reactivity Data

•••••	riououng Duiu		
Stability	Unstable		Conditions to Avoid
-			KEEP FROM CONTACT WITH OXIDIZING MATERIALS
	Stable	XXXXX	
Incompatibility (Material to Avoid)		
ACIDIC IN NATU	JRE – AVOID ALKALI	NE CONTA	CT
Hazardous Deco	mposition or Byprodu	cts	
UNKNOWN			
Hazardous	May Occur		Conditions to Avoid
Polymerization			NONE SPECIAL

Will Not Occur	XXXXX	

Section VI - Health Hazard Data

Routes(s) of Entry:	Inhalation?	Skin?	Ingestion?
		- LOW ACUTE DERMAL TOXICITY-	LOW ACUTE ORAL TOXICITY
Health Hazards (Acute a			
NONE KNOW	N AT THIS TIME		
<u> </u>			
Carcinogenticity:	NTP?	IARC Monographs?	OSHA Regulated?
		REDIENT DESIGNATED BY IARC, NT	P, AOGIH OR OSHA AS A
	JMAN CARCINOGEN.		
Signs and Symptoms of E			107
EXPOSURE L	IMITS IN AIR: NO EXPOSURE LIMIT	TS ESTABLISHED FOR THIS PRODU	
Madical Conditions Core	rolly Aggrovated by Evenours		
NONE KNOW	rally Aggravated by Exposure		
	IN		
Emergency and First Aid	Procedures		
		AL ATTENTION IF IRRITATION DEVE	I OPES OR PERSISTS
		NATER. INHALATION- SEEK MEDIC	
		ATTER. INHALATION- SEEK MEDIC ATTENTION. NOTE TO PHYSICIAN	
INGESTION: I	NDUCE VOMITING-SEEK MEDICAL	ATTENTION. NOTE TO PHYSICIAN	
INGESTION: I Section VII – Prec	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar	ATTENTION. NOTE TO PHYSICIAN	
INGESTION: I Section VII – Prec Steps to Be Taken in Cas	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar e Material is Released or Spilled	ATTENTION. NOTE TO PHYSICIAN	I: TREAT SYMPTOMATICALLY
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPRO	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar se Material is Released or Spilled OPRIATE PROTECTIVE GEAR. ABS	ATTENTION. NOTE TO PHYSICIAN nd Use SORB ONTO VERMICULITE. SWEEF	2 UP INTO APPROPRIATE
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPRO CONTAINER	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar be Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER	ATTENTION. NOTE TO PHYSICIAN	2 UP INTO APPROPRIATE
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPRO	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar be Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER	ATTENTION. NOTE TO PHYSICIAN nd Use SORB ONTO VERMICULITE. SWEEF	2 UP INTO APPROPRIATE
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR(CONTAINER LIKE PAINT T	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar be Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER	ATTENTION. NOTE TO PHYSICIAN nd Use SORB ONTO VERMICULITE. SWEEF	2 UP INTO APPROPRIATE
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR CONTAINER LIKE PAINT T Waste Disposal Method	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar ie Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATEF HINNER.	ATTENTION. NOTE TO PHYSICIAN Id Use SORB ONTO VERMICULITE. SWEEP RIAL PICKUP IS COMPLETE WITH A	: TREAT SYMPTOMATICALLY PUP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR CONTAINER LIKE PAINT T Waste Disposal Method	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar ie Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATEF HINNER.	ATTENTION. NOTE TO PHYSICIAN nd Use SORB ONTO VERMICULITE. SWEEF	: TREAT SYMPTOMATICALLY PUP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR CONTAINER LIKE PAINT T Waste Disposal Method DISPOSE OF	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar ie Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATEF HINNER.	ATTENTION. NOTE TO PHYSICIAN Id Use SORB ONTO VERMICULITE. SWEEP RIAL PICKUP IS COMPLETE WITH A	: TREAT SYMPTOMATICALLY PUP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR CONTAINER LIKE PAINT T Waste Disposal Method DISPOSE OF Precautions to Be Taken	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar ise Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER HINNER. IN ACCORDANCE WITH LOCAL, S in Handling and Storing	ATTENTION. NOTE TO PHYSICIAN Id Use SORB ONTO VERMICULITE. SWEEP RIAL PICKUP IS COMPLETE WITH A	: TREAT SYMPTOMATICALLY P UP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR CONTAINER LIKE PAINT T Waste Disposal Method DISPOSE OF Precautions to Be Taken STORE AT R	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar se Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER HINNER. IN ACCORDANCE WITH LOCAL, S in Handling and Storing DOM TEMPERATURE IN TIGHTLY O	ATTENTION. NOTE TO PHYSICIAN ad Use SORB ONTO VERMICULITE. SWEEP RIAL PICKUP IS COMPLETE WITH A TATE AND FDERAL REGULATIONS CLOSED CONTAINERS. AVOID DIRE	E TREAT SYMPTOMATICALLY P UP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR(CONTAINER LIKE PAINT T Waste Disposal Method DISPOSE OF Precautions to Be Taken STORE AT R(CONTACT WI	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar se Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER HINNER. IN ACCORDANCE WITH LOCAL, S in Handling and Storing DOM TEMPERATURE IN TIGHTLY O TH SKIN AND EYES. WASH HANDS	ATTENTION. NOTE TO PHYSICIAN ad Use SORB ONTO VERMICULITE. SWEEF RIAL PICKUP IS COMPLETE WITH A TATE AND FDERAL REGULATIONS CLOSED CONTAINERS. AVOID DIRE S THOROUGHLY AFTER HANDLING	E TREAT SYMPTOMATICALLY P UP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR CONTAINER LIKE PAINT T Waste Disposal Method DISPOSE OF Precautions to Be Taken STORE AT R CONTACT WI	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar se Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER HINNER. IN ACCORDANCE WITH LOCAL, S in Handling and Storing DOM TEMPERATURE IN TIGHTLY O	ATTENTION. NOTE TO PHYSICIAN ad Use SORB ONTO VERMICULITE. SWEEF RIAL PICKUP IS COMPLETE WITH A TATE AND FDERAL REGULATIONS CLOSED CONTAINERS. AVOID DIRE S THOROUGHLY AFTER HANDLING	E TREAT SYMPTOMATICALLY P UP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPR(CONTAINER LIKE PAINT T Waste Disposal Method DISPOSE OF Precautions to Be Taken STORE AT R(CONTACT WI	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar se Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER HINNER. IN ACCORDANCE WITH LOCAL, S in Handling and Storing DOM TEMPERATURE IN TIGHTLY O TH SKIN AND EYES. WASH HANDS	ATTENTION. NOTE TO PHYSICIAN ad Use SORB ONTO VERMICULITE. SWEEF RIAL PICKUP IS COMPLETE WITH A TATE AND FDERAL REGULATIONS CLOSED CONTAINERS. AVOID DIRE S THOROUGHLY AFTER HANDLING	E TREAT SYMPTOMATICALLY P UP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPRO CONTAINER LIKE PAINT T Waste Disposal Method DISPOSE OF Precautions to Be Taken STORE AT RO CONTACT WI WITH SOILED Other Precautions	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar se Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER HINNER. IN ACCORDANCE WITH LOCAL, S in Handling and Storing DOM TEMPERATURE IN TIGHTLY O TH SKIN AND EYES. WASH HANDS	ATTENTION. NOTE TO PHYSICIAN ad Use SORB ONTO VERMICULITE. SWEEF RIAL PICKUP IS COMPLETE WITH A TATE AND FDERAL REGULATIONS CLOSED CONTAINERS. AVOID DIRE S THOROUGHLY AFTER HANDLING SMOKE IN THE WORK AREA .	E TREAT SYMPTOMATICALLY P UP INTO APPROPRIATE N APPROPRIATE SOLVENT
INGESTION: I Section VII – Prec Steps to Be Taken in Cas WEAR APPRO CONTAINER LIKE PAINT T Waste Disposal Method DISPOSE OF Precautions to Be Taken STORE AT RO CONTACT WI WITH SOILED Other Precautions	NDUCE VOMITING-SEEK MEDICAL autions for Safe Handling ar se Material is Released or Spilled DPRIATE PROTECTIVE GEAR. ABS WASH SPILL AREA AFTER MATER HINNER. IN ACCORDANCE WITH LOCAL, S in Handling and Storing DOM TEMPERATURE IN TIGHTLY O TH SKIN AND EYES. WASH HANDS HANDS. DO NOT EAT, DRINK OR	ATTENTION. NOTE TO PHYSICIAN ad Use SORB ONTO VERMICULITE. SWEEF RIAL PICKUP IS COMPLETE WITH A TATE AND FDERAL REGULATIONS CLOSED CONTAINERS. AVOID DIRE S THOROUGHLY AFTER HANDLING SMOKE IN THE WORK AREA .	E TREAT SYMPTOMATICALLY P UP INTO APPROPRIATE N APPROPRIATE SOLVENT

Section VIII – Control Measures Respiratory Protection (Specific Type) NO SPECIAL RESPIRATORY PROTECTION REQUIRED. Ventilation Local Exhaust Special USE LOCAL EXHAUST AS NEEDED. MAINTAIN SAFETY EQUIPMENT. NORMAL Mechanical (General) PROVIDE ADEQUATE VENTILATION. Other N/A Protective Gloves Eye Protection SAFETY GLASSES WITH SIDE SHIELDS RECOMMENDED OR AS REQUIRED Other Protective Clothing or Equipment WORK CLOTHING Work/Hygienic Practices CLEAN AS NORMAL